

03560.002446.1



PATENT

Cafe \$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
MASATO MINAMI ET AL.)
Appln. No.: 10/054,884)
Filed: January 25, 2002)
For: METHOD FOR MANUFACTURING)
CATHODE, ELECTRON SOURCE,)
AND IMAGE FORMING APPARATUS)
U.S. Patent No.: 6,783,414 B2)
Issued: August 31, 2004)

Examiner: J.L. Williams
Group Art Unit: 2879
August 2, 2005

Certificate
AUG 10 2005
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

08/05/2005 EFLORES 00000020 6783414

01 FC:1811

100.00 DP

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

AUG 10 2005

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

A handwritten signature in dark ink, appearing to read 'Frank A. DeLucia', is written over a horizontal line.

Frank A. DeLucia
Attorney for Patentees
Registration No. 42, 476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,783,414 B2

DATED : August 31, 2004

INVENTOR(S) : MASATO MINAMI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [75]:

Inventors, "Masato Minami, Kanagawa-ken (JP); Takashi Iwaki, Tokyo (JP)"
should read --Masato Minami, Atsugi (JP); Takashi Iwaki, Machida
(JP)--.

COLUMN 7:

Line 15, " Ω/\square " should read -- Ω/\square --.

COLUMN 9:

Line 13, "beat" should read --heat--.

COLUMN 10:

Line 40, "1 psec" should read --1 μ sec--; and
Line 41, "10 psec" should read --10 μ sec--.

COLUMN 13:

Line 13, "preferably" should read --preferable--;
Line 24, "wires;" should read --wires--; and
Line 48, "y-" should read --Y- --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,783,414 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,783,414 B2

DATED : August 31, 2004

INVENTOR(S) : MASATO MINAMI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 22, "are" (1st occurrence) should read --or--.

COLUMN 16:

Line 7, "Dox," should read --Dox₁--; and

Line 63, "vth" should read --Vth--.

COLUMN 24:

Line 23, "cess" should read --cesses--.

COLUMN 30:

Line 11, "100 μ m" should read --100 nm--.

COLUMN 35:

Line 55, "ahs" should read --has--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,783,414 B2

No. of add'l. copies
@ 30¢ per page



AUG 10 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,783,414 B2

DATED : August 31, 2004

INVENTOR(S) : MASATO MINAMI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [75]:

Inventors, "Masato Minami, Kanagawa-ken (JP); Takashi Iwaki, Tokyo (JP)"
should read --Masato Minami, Atsugi (JP); Takashi Iwaki, Machida
(JP)--.

COLUMN 7:

Line 15, " Ω/\square " should read -- Ω/\square --.

COLUMN 9:

Line 13, "beat" should read --heat--.

COLUMN 10:

Line 40, "1 psec" should read --1 μ sec--; and
Line 41, "10 psec" should read --10 μ sec--.

COLUMN 13:

Line 13, "preferably" should read --preferable--;
Line 24, "wires;" should read --wires--; and
Line 48, "y-" should read --Y- --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,783,414 B2

No. of add'l. copies
@ 30¢ per page



AUG 10 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,783,414 B2

DATED : August 31, 2004

INVENTOR(S) : MASATO MINAMI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 22, "are" (1st occurrence) should read --or--.

COLUMN 16:

Line 7, "Dox," should read --Dox₁--; and

Line 63, "vth" should read --Vth--.

COLUMN 24:

Line 23, "cess" should read --cesses--.

COLUMN 30:

Line 11, "100 μ m" should read --100 nm--.

COLUMN 35:

Line 55, "ahs" should read --has--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,783,414 B2

No. of add'l. copies
@ 30¢ per page



AUG 10 2005